good condition.

SECRET

INFORMA	TION REPORT	ing of Title 18, Sections 793 an amended. Its transmission or	This Document contains information affecting the National Defense of the United States, within the meaning of Title 18. Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited		
	SECRET	hw law The reproduction of	sed person is prohibited this form is prohibited 25X1		
COUNTRY	Czechoslovakia	REPORT			
SUBJECT	Czechoslovak Autombbile Works, National Corporation (AZNP)	DATE DISTR.	2 March 1953 25X1		
DATE OF INFO.		NO. OF PAGES	RD 25X		
PLACE ACQUIRED	This is UNEVALUATED Info	REFERENCES ormation			
	THE SOURCE EVALUATIONS IN TH THE APPRAISAL OF CONT. (FOR KEY SEE R	ENT IS TENTATIVE.	25X1		
2. The m CAZNP Eng. The c the p 3. The p The e plant 4. The p	Clant of the Czechoslovak Automobily, n.p AZNP) at Horni Hanychovale end of 1951. It is located in a was rebuilt for this purpose. To whom are women. A small percentianager of the plant is Simon (find a pradny (fnu), a production expert thairman of the shop committee is clant's Communist Party organization at Rynovice, where the vehicles at Rynovice, where the vehicles clant has the following department of the locks; work is done in three sof German origin.	i(051/G16) was opened assorpthe former textile factory he plant employs 600 people tage of the employees are Gu), a former worker and emp Boleslav. The manager's d. The cadre officer is Fradorky (fnu), and the chairma on is Josef Pokorny. The 706 Avia type for busses (Automobile Works National are assembled. B. e shifts and most of the mager is a second and most of the mager is a second and most of the mager is a second in the mager is a se	ened Rotex, , about ermans. loyee of the eputy is ntisek Drbohlav. n of and trucks. Corporation)		
W	ylinder heads; head, Ladislav Bod. ith machinery of both Czech and Go 952, one three-spindle milling mac	erman origin. At the end of	f September		

25 YEAR _• SRE-REVIEW X NAVY Washington Distribution Indicated By "X"; Field Distribution By "#".)

of cast iron instead of aluminum since September 1952.

25X1

This is the key department of the factory and at the same time the worst bottleneck in production. It is well supplied with material, but there is a shortage of tools. Castings from the foundries arrive in very

c. Gear boxes; owing to the shortage of aluminum, gear boxes have been manufactured

SECRET		25X1
	-2-	05)//

- d. Cylinders; this department is fulfilling its production plant only 30%, the worst performance in the entire factory. Part of its production goes to the USSR. This factor have a great and the control of the same time.
- e. Crankshafts; foreman, Delis (fnu); this department is well equipped with machine tools and fulfilled its plan 60%.
- f. Flywheels; this department is poorly equipped with machine tools.
- g. Valve rockers.
- h. Valve guides.
- i. Welding shop.
- j. Tool shop, grinding shop, repairs to machinery, issuing of tools.
- k. Assembly.
- 5. In September 1952, a Soviet delegation of eight members visited the factory. They were shown around by the manager, the chairman of the shop committee and the chairman of the plant's Communist Party organization.
- 6. The plant has a Doslet organization consisting of 20 parachutists, of whom three are women, and about 25 glider pilots. They practice three times a week at the airfield at Liberec, jumping from Junkers 52 planes. The secretary of Doslet for the Liberec district is Capt. of the Air Force Benes (fnu).

	· ·	
		25X1
だいいしゅう /		